


TRAILER MUD FLAP RETENTION SYSTEM

INNOVATIVE SPRING STEEL MOUNTING BRACKET



- Virtually **ELIMINATE** Trailer Mud Flap Loss
- Install and Repair with Common Hand Tools
- **NO MORE WELDING** - Makes Roadside or Driver Repair Possible

Part Number	Description
TRSD10NT	TMF-RS, DIRECT FLEX HANGERS, WITHOUT CONSPICUITY, PAIR
TRSLD10NT	TMF-RS, DIRECT FLEX HANGERS, WITHOUT CONSPICUITY, LEFT HAND
TRSRD10NT	TMF-RS, DIRECT FLEX HANGERS, WITHOUT CONSPICUITY, RIGHT HAND
TRSDS10NT	TMF-RS, SPRING LOADED HANGERS, WITHOUT CONSPICUITY, PAIR
TRSLD10NT	TMF-RS, SPRING LOADED HANGERS, WITHOUT CONSPICUITY, LEFT HAND
TRSRD10NT	TMF-RS, SPRING LOADED HANGERS, WITHOUT CONSPICUITY, RIGHT HAND
TRSD10WT	TMF-RS, DIRECT FLEX HANGERS, WITH CONSPICUITY, PAIR
TRSLD10WT	TMF-RS, DIRECT FLEX HANGERS, WITH CONSPICUITY, LEFT HAND
TRSRD10WT	TMF-RS, DIRECT FLEX HANGERS, WITH CONSPICUITY, RIGHT HAND
TRSDS10WT	TMF-RS, SPRING LOADED HANGERS, WITH CONSPICUITY, PAIR
TRSLD10WT	TMF-RS, SPRING LOADED HANGERS, WITH CONSPICUITY, LEFT HAND
TRSRD10WT	TMF-RS, SPRING LOADED HANGERS, WITH CONSPICUITY, RIGHT HAND

Ensure Safe & Legal Operation

APPLICATION

48" Wide Slider with Available
2" or 2 7/8" Hole Centers

CHOOSE FROM TWO OPTIONS



AVAILABLE

- Left Hand Replacement/Installation
- Right Hand Replacement/Installation
- Complete System Retrofit
- Available with and without conspicuity tape



**HIGH BAR
BRANDS**

A DIVISION OF **HIGH BAR BRANDS, LLC**
2843 South Maple Avenue Fresno, CA 93725
(559) 226-9049 | (800) 255-5387
www.highbarbrands.com